

Australian Investigations Projects

Listed below are some of our projects for building related investigations

Year	Client	Project
1994	Boncorp	Infra-red survey of concrete water tank for voids. Mt. Martha. Victoria.
	Maritime Services NSW	Half cell testing to wharf in Botany Bay NSW
	Ministry of Housing	TAFE College. Specification & control of repair works. Geelong Victoria
	Adelaide Brighton Cement	Investigation & recommendations for repairs. Adelaide. South Australia
	FAC	Measurement of moisture content of floor slabs. Tullamarine. Victoria.
	Pasminco	Inspection of Telfor pit at Point Pirie Plant Point Pirie. South Australia
	Ministry of Works	Investigation of water leakage at 2 Treasury Place. Melbourne
	National Mutual	Investigation of facade producer of Specifications & Quality Control Auditor for the 1.8 million restoration to the National Mutual Centre Building. Melbourne
	National Mutual Carlton & United Breweries	Investigation & recommendations for repairs to the Boiler House for the CUB Plant. Abbotsford. Victoria
	National Mutual	Investigation with recommendations for repair to 191 Queen Street. Melbourne

Year	Client	Project
	FAC	Investigation of pre-cast units removed from Tullamarine Airport. Victoria
	Raddison Hotel	Investigation of the Raddison Hotel car park including specification for the repairs. Melbourne
	ICI	Investigation of the Resin Test Laboratory including recommendations for repairs
	Huntsman Chemicals	Investigation of tank & water tower with recommendations for remedial repairs
	Multicon	Investigation & introduction of asset management program for concrete tanks. BHP. Whyalla. South Australia
	GEON	Investigation of industrial plant including recommendations for repairs Kororoit Creek Road, Victoria
	Eso Australia limited	Investigation of concrete plinths to oil burner with recommendations for repairs. Longford. Gas Plant. Victoria
	Remedial Engineering	Investigation at 264 Bay Street. Port Melbourne with recommendations for repairs. Victoria
	AMP	Investigation of facade to the Grenfell Centre with recommendations for complete repairs or renewal of facade. Adelaide
	Vline	Investigation of three (3) bridges at Ringwood. Bendigo & Glenferrie. Victoria
	Carlow House Ply Ltd	Investigation & recommendations for remedial repairs to Carlow House. Melbourne
	Remedial Engineering	Investigation with DBTS™ and UPV testing office damaged concrete slab. Brisbane

Year	Client	Project
	Howard Floreys P/ L	Investigation & recommendations for remedial repairs to facade of the Howard Floreys Building, Melbourne University
1995	1 Collins Street P/L	Investigation with recommendations for remedial repairs for facade at 1 Collins Street,
	Port of Melbourne Auth.	Melbourne Detailed investigation of Long Island Point Wharf with recommendations for remedial repairs Hastings, Victoria
	Remedial Engineering	Investigation of facade at 30 Collins Street. Melbourne
	AGC	Investigation & testing with recommendations for remedial repairs at 277 William Street. Melbourne
	Obyashi- Transfield JV	Investigation of 9 no. bridges for the Transurban Toll Group with recommendations for repairs. Melbourne
	Powercor Australia	Investigation & testing of wharf to Newport Power Station, Williamstown, Victoria
	Mitchell Industries	Investigation with recommendations for repairs to quarry buildings, Lilydale, Victoria
	Ballarat Shire	Investigation with recommendations for repairs to the Ballarat Car Park, Ballarat. Victoria
	Stafford Holdings PIL	Investigation of suspended floor slabs at a factory in Glen Waverley , Victoria
	Seymour Sports & Entertainment Centre	Investigation & expert witness for investigation of floor slab , Seymour, Victoria
1996	Smorgon Steel	Integrity Testing Pty Limited Investigation of furnace floor using DBTS™ system. North Laverton

Year	Client	Project
	Port of Melbourne Auth. Smorgon Steel/ John Holland	Durability system to determine condition of wharf in 10 years time. Crib Point Wharf Hastings. Victoria 'Specification & control of repairs to furnace floor
	Thiess Contractors	Infra-red survey of 8,000m ² Neerabup Reservoir to identify honeycombed concrete.
	Thiess Contractors	Western Australia Production of repair strategies for the 8000m ² Neerabup Reservoir. Western Australia
	BHAS	Investigation of water leakage below lead smelter with production of repair strategy. Port Pirie. SA
	Nth Melbourne City Council	Infra-red survey to determine leakage of a swimming pool. Victoria
	Obyashi- Tran\field JV	Detailed investigation of the foundations to the Wallace Crescent Bridge. Victoria
	Coopersmith Holdings	Detailed investigation of incomplete concrete slabs for warehouse development. Victoria
	Coopersmith Holdings	Expert witness in arbitration for incomplete work to concrete slabs. Victoria
	Rockman & Rockman	Condition survey to large warehouse complex Geelong Road. Victoria
	Swissnec Equipment	Construction methodology for construction of new concrete slabs incorporating under floor heating
	Koppers-Hickson	Investigation & preparation of repair systems for concrete structures at an arsenic acid farm. Victoria

Year	Client	Project
1997	Port of Melbourne Auth.	Structural analysis of critical beam elements to the Crib Point Wharf: Victoria
	Port of Brisbane Auth.	Structural analysis using the DBTS™ system of concrete wharf at Fisherman Island. Brisbane. Queensland
	Esperance Shire Council	Quality Control & secondment of personnel for repair of timber piling
	Education Department	Moisture content of concrete floor
	Brisbane Port of Brisbane Auth	Structure analysis using the DBTS™ system for Remedial Group/ control of repairs to Fisherman Islands Wharf: